

# Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.  
Wood Village, OR 97060  
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

## Vehicle Description

**2007 Chevrolet Tahoe 4WD 4D SUV 4WD LS 5.3L**

<b>VIN</b>	1GNEK13037J139956		
<b>Ext. Color</b>	Silver		
<b>Int. Color</b>	Tan	<b>Interior</b>	Cloth
<b>Mileage</b>	47,832 <b>Actual Miles</b>		
<b>Engine</b>	5.3L 8-Cylinder Gas		
<b>Transmission</b>	Automatic		



## Auction Data

<b>Sale Date</b>	To Be Announced		
<b>Run #</b>	To Be Announced	<b>Inv #</b>	6949
<b>Consignor</b>	GSA FLEET SERVICES		

## Declarations

<b>Warranty</b>	GSA Regular Terms
<b>Mileage</b>	47,832 <b>Actual Miles</b>
<b>Title</b>	Clear Title

## Equipment

- 4 Wheel Drive
- Automatic Transmission
- 8 Cylinder Gas
- Air Conditioning
- No Third Row Seat
- 5 Passenger
- Rear Air Conditioning
- Anti-Theft System
- Electronic Traction Control
- Power Windows
- Power Locks
- Trip Counter
- Cruise Control
- Dual Air Bag
- Anti Lock Brakes
- Tilt Steering Wheel
- Alloy Wheels
- AM/FM CD
- Roof Rack
- Keyless Entry
- Running Boards
- Towing Package
- Hard Top
- Rear Defog
- Rear Wiper
- Tinted Windows
- Power Steering
- Power Brakes
- Electric Mirrors
- Rear Heater

## Damage Descriptions (CR completed on 9/8/2015 by NATE HALL)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
<b>Interior</b>									
1	Carpeting	Stained	Multiple Instances						--
<b>Interior Subtotal</b>				--	--	--	--	--	--
						--	--	--	--

# 2007 Chevrolet Tahoe 4WD 4D SUV 4WD LS 5.3L

VIN: 1GNEK13037J139956

Inv#: 6949

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
---	----------	---------------	----------	----------	----------	--------------	-------------	------------	-------

## Left

2	Exterior Left	Light Scratch	Multiple Instances						--
---	---------------	---------------	--------------------	--	--	--	--	--	----

### Left Subtotal

--	--	--	--	--	--
		--	--	--	--

## Rear



3	Deck Lid	Hole(S)	1 To 2 Inches						--
---	----------	---------	---------------	--	--	--	--	--	----



4	Rear Bumper/Cover	Gouged	Multiple Instances						--
---	-------------------	--------	--------------------	--	--	--	--	--	----

### Rear Subtotal

--	--	--	--	--	--
		--	--	--	--

## Right

5	Exterior Right	Scratched	Multiple Instances						--
---	----------------	-----------	--------------------	--	--	--	--	--	----

### Right Subtotal

--	--	--	--	--	--
		--	--	--	--

### Total

--	--	--	--	--	--
		--	--	--	--

## Tires

Region	Brand	Size	Tread Depth
Left Front	GOODYEAR	/-	Average (Average)
Left Rear	GOODYEAR	/-	Average (Average)
Right Front	GOODYEAR	/-	Average (Average)
Right Rear	GOODYEAR	/-	Average (Average)
Spare	GOODYEAR	/-	Average (Average)

## Miscellaneous

Coolant level	OK
Fuel level	1/4
Interior odor	OK
Oil level	OK
Transmission fluid level	OK

## 2007 Chevrolet Tahoe 4WD 4D SUV 4WD LS 5.3L

VIN: 1GNEK13037J139956

Inv#: 6949

### Images



## 2007 Chevrolet Tahoe 4WD 4D SUV 4WD LS 5.3L

VIN: 1GNEK13037J139956

Inv#: 6949

---

